







COPY KEMENKES

HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
<p data-bbox="226 646 575 776">Tanda evakuasi di area assembling nursing bed baru terpasang satu di dalam ruangan</p>		<p data-bbox="1031 646 1402 776">Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area assembling nursing bed</p>	
			
			

COPY KEMENKES

HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
<p>Tanda evakuasi di area gudang bahan baku baru terpasang satu di luar ruangan</p>		<p>Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area gudang bahan baku</p>	
			
			

COPY KEMENKES

HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
<p>Tanda evakuasi di area gudang bahan baku baru terpasang satu di luar ruangan</p>		<p>Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area gudang bahan baku</p>	

Cimahi, 05 Desember 2023
Mengetahui,



Diah N.K.
HCGA Manager