







HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
<p data-bbox="226 646 571 776">Tanda evakuasi di area assembling nursing bed baru terpasang satu di dalam ruangan</p>		<p data-bbox="1031 646 1400 776">Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area assembling nursing bed</p>	
			
			

HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
<p>Tanda evakuasi di area gudang bahan baku baru terpasang satu di luar ruangan</p>		<p>Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area gudang bahan baku</p>	
			
			

HASIL TEMUAN	BEFORE	HASIL PERBAIKAN	AFTER
Tanda evakuasi di area gudang bahan baku baru terpasang satu di luar ruangan		Tanda evakuasi di area assembling sudah terpasang di beberapa titik di area gudang bahan baku	

Cimahi, 05 Desember 2023
Mengetahui,



Diah N.K.
HCGA Manager