

Order No./계약번호 : 01S6325784

PO No./주문번호

Supplier /주문자 : POSCO INTERNATIONAL CORPORATION

Commodity /품명 : COLD ROLLED STEEL IN COIL

Customer /고객사 : POSCO IJPC

Spec & Type /규격 : JIS G3141 SPCC-S

Size/치수	Product No./제품번호	Quantity/수량	Weight/중량 (kg)	Heat No./재강번호	Country of Mill & Pour	Position	Tensile Test /인장시험			Division	Chemical Composition/화학성분				
							YP (N/mm <sup>2</sup> )	TS (%)	EL (%)		C (%)	Si (%)	Mn (%)	P (%)	S (%)
1.2x1219xC	CSW7717A	1	14,830	SP63189	KOR	B	149	290	52	L	0.0018	0.004	0.092	0.0100	0.0047
1.2x1219xC	CSW7717B	1	14,700	SP63189	KOR	B	149	290	52	L	0.0018	0.004	0.092	0.0100	0.0047
1.2x1219xC	CSW7720A	1	14,900	SP63189	KOR	B	149	290	52	L	0.0018	0.004	0.092	0.0100	0.0047
1.2x1219xC	CSW7720BB	1	13,810	SP63189	KOR	B	149	290	52	L	0.0018	0.004	0.092	0.0100	0.0047
1.2x1219xC	CSWA199B	1	14,700	SP63189	KOR	B	156	292	52	L	0.0018	0.004	0.092	0.0100	0.0047
1.2x1219xC	CSWA205A	1	14,710	SP63195	KOR	B	155	293	50	L	0.0015	0.003	0.099	0.0103	0.0059
1.2x1219xC	CSWA205B	1	14,840	SP63195	KOR	B	155	293	50	L	0.0015	0.003	0.099	0.0103	0.0059
1.2x1219xC	CSWA207B	1	14,820	SP63195	KOR	B	155	293	50	L	0.0015	0.003	0.099	0.0103	0.0059
1.2x1219xC	CSWA388A	1	14,590	SP63195	KOR	B	151	285	52	L	0.0015	0.003	0.099	0.0103	0.0059
1.2x1219xC	CSWA388B	1	14,850	SP63195	KOR	B	151	285	52	L	0.0015	0.003	0.099	0.0103	0.0059
*** Sub Total (010) ***		10	146,150 (kg)				< Not Welded >								
*** Grade Total ***		10	146,150 (kg)												
*** Grand Total ***		10	146,150 (kg)												
<p>=== Last Item ===</p>															

\* Position - T : Top, M : Middle, B : Bottom  
 \* Tensile Test Direction : Longitudinal, Gauge Length : 50 mm(Rectangular), YP Method : Upper Point  
 \* Division - L : Ladle Analysis

We, POSCO, hereby certify that the products specified in the present MTC have been fully processed in South Korea. (Facility and address information is stated below)  
 We hereby certify that the material herein has been made in accordance with the order and is fully in compliance.

Legal sanction can be imposed on forging. Improper use of product can cause safety issues.

Surveyor To :

Park, Junyoung

